

Lampiran 4 Faktor Kondisi Lapangan dalam Mempengaruhi Penyelesaian Pekerjaan Struktur

Pekerjaan	Responden ke- (%)														rata-rata (%)
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	
Baja Tulangan U24 Polos	25	25	30	20	30	30	30	25	30	30	20	30	30	30	28
Baja Tulangan U24 Polos lanjutan	20	15	15	25	15	20	20	15	25	25	15	20	25	15	19
Beton mutu sedang, fc' 20 Mpa	30	30	30	30	30	30	25	30	30	25	30	30	25	25	29
Beton mutu sedang, fc' 20 Mpa lanjutan	15	25	15	15	15	25	10	25	25	25	20	20	10	15	19
Baja Tulangan U32 Polos	10	10	15	10	10	15	15	15	5	10	15	15	10	15	12
Dinding Sumuran Silinder terpasan, diameter 3,50 m	30	20	30	30	30	30	30	30	25	25	25	25	30	20	27
Beton Siklop, fc' 15 Mpa	30	20	30	25	25	30	30	25	30	30	30	30	30	25	28
Beton mutu sedang, fc' 30 Mpa	15	20	20	15	15	10	20	20	15	20	20	20	20	15	18
Beton mutu rendah, fc' 10 Mpa	10	5	15	10	10	15	15	10	15	10	10	10	15	10	11
Perletakan Elastomerik Sintetis Ukuran (600x380x60)	10	10	10	10	5	10	10	5	10	10	10	10	10	10	9
Penyediaan Unit Pracetak Gelagar Tipe I bentang 20 meter	10	10	10	5	10	5	10	10	10	10	10	10	5	10	9
Pemasangan Unit Pracetak Gelagar Tipe I bentang 20 meter	5	5	10	5	5	10	10	5	10	10	10	5	5	5	7
Beton mutu rendah, fc' 15 Mpa	15	15	5	20	20	20	20	20	20	20	15	15	15	15	17
Baja Prategang	20	15	20	10	25	25	15	15	25	15	15	20	15	25	19

