

B. Tabel Koefisien Kontrol

Ukuran Contoh (n)	Koefisien Untuk Batas Kontrol X-Bar	Koefisien untuk Batas Kontrol R		Koefisien Untuk Simpangan Baku, s
	A_2	D_3	D_4	d_2
2	1,880	0	3,267	1,128
3	1,023	0	2,574	1,693
4	0,729	0	2,282	2,059
5	0,577	0	2,114	2,326
6	0,483	0	2,004	2,534
7	0,419	0,076	1,924	2,704
8	0,373	0,136	1,864	2,847
9	0,337	0,184	1,816	2,970
10	0,308	0,223	1,777	3,078
11	0,285	0,256	1,744	3,173
12	0,266	0,283	1,717	3,258
13	0,249	0,307	1,693	3,336
14	0,235	0,328	1,672	3,407
15	0,223	0,347	1,653	3,472
16	0,212	0,363	1,637	3,532
17	0,203	0,378	1,622	3,588
18	0,194	0,391	1,608	3,640
19	0,187	0,403	1,597	3,689
20	0,180	0,415	1,585	3,735