

Lampiran 1 Hasil *Instrument* Survei Kondisi Jalur Kereta Non Aktif

Lokasi	Koordinat (Universal Transverse Mercator)			Kondisi Prasarana Jalan Rel		
	Nama Lokasi	North	East	Zone	Beralih Fungsi	Rusak
Stasiun Tugu	430119.9737	9138948.385	49	-	-	√
Kampung Pringgo Kusuman (Jl. Jlagranlor)	429245.8004	9138881.839	49		√	
Jl. Letjen Suprpto	429060.593	9138136.4	49	√		
Taman Parkir Ngabean (Sta. Ngabean)	429019.8019	9137409.975	49		√	
Jl. Suryowijayan (Pasar Taman Sari)	428983.3304	9136744.363	49	√		
Jl. Bantul	428949.7205	9135650.897	49	√		
Jl. Bantul KM 1 (Sta. Dongkelan)	428836.1091	9134964.159	49	√		
JL Bantul KM 4	428702.9986	9134055.171	49		√	
Dusun Kweni (Jembatan Winongo)	428342.089	9133594.693	49	√		
Desa Tirtonimolo (Sta. Winongo)	428032.7576	9133292.391	49	√		
Jl. Bantul KM 5	427941.6454	9133039.071	49		√	
JL Bantul	427420.1464	9131649.647	49	√		
Jl. Bantul KM 9 (Stasiun Cepit)	427043.1444	9130370.668	49	√		
Jl. Bantul KM 10	426679.8705	9129208.456	49	√		
Jl. Jenderal Sudirman (Sta. Bantul)	426092.9749	9128097.51	49	√		
Jl. KH. Wahid Hasyim	425407.8773	9127062.681	49	√		
Jl. KH. Wahid Hasyim (Perempatan Palbabang)	425173.3986	9126188.885	49	√		
Terminal Palbabang (Sta. Palbabang)	424864.8986	9126096.617	49	√		