

DAFTAR ISI

HALAMAN JUDUL	i
HALAMAN PERNYATAAN KEASLIAN	ii
SURAT KETERANGAN MAGANG	iii
LEMBAR PENGESAHAN PEMBIMBING.....	iv
LEMBAR PENGESAHAN PENGUJI.....	v
HALAMAN PERSEMBAHAN	vi
HALAMAN MOTTO.....	vii
KATA PENGANTAR	viii
ABSTRAK.....	ix
DAFTAR ISI.....	x
DAFTAR GAMBAR.....	xii
DAFTAR TABEL.....	xiii
BAB I PENDAHULUAN.....	1
1.1 Latar Belakang	1
1.2 Rumusan Masalah.....	4
1.3 Tujuan Penelitian	4
1.4 Manfaat Penelitian	5
1.5 Batasan Penelitian.....	5
1.6 Sistematika Penulisan	6
BAB II TINJAUAN PUSTAKA	7
2.1 Kajian Induktif.....	7
2.2 Kajian Deduktif.....	11
2.3 Overall Labor Effectiveness (OLE)	11
2.4 Root Cause Analysis (RCA)	14
BAB III METODE PENELITIAN	16
3.1 Objek Penelitian.....	16
3.2 Sumber Data.....	16
3.3 Metode Pengumpulan Data.....	17
3.3.1 Wawancara.....	17
3.3.2 Observasi.....	17
3.3.3 Studi Pustaka.....	17
3.3.4 Teknik Pengolahan Data	18
3.3.4.1 Availability Ratio.....	18
3.3.4.2 Performance Ratio	18
3.3.4.3 Quality Ratio.....	18
3.3.4.4 Overall Labor Effectiveness	18
3.4 Metode Analisis Data.....	19
3.5 Alur Penelitian	19
BAB IV PENGUMPULAN DAN PENGOLAHAN DATA.....	21
4.1 Pengumpulan Data	21
4.1.1 Sejarah PT Yamaha Indonesia	21
4.1.2 Proses Produksi	21
4.1.3 Data OLE Kelompok Kerja Sub Assy Side Glue UP	22
4.1.3.1 Availability Ratio.....	22
4.1.3.2 Performance Ratio	24

4.1.3.3 Quality Ratio.....	25
4.1.4 Data OLE Kelompok Kerja <i>Stringing Strungback</i>	26
4.1.4.1 Availability Ratio.....	26
4.1.4.2 Performance Ratio	27
4.1.4.3 Quality Ratio.....	28
4.2 Pengolahan Data	29
4.2.1 Kelompok Kerja Sub Assy Side Glue UP.....	29
4.2.1.1 Availability Ratio.....	29
4.2.1.2 Performance Ratio	31
4.2.1.3 Quality Ratio.....	32
4.2.1.4 Overall Labor Effectiveness	33
4.2.2 Kelompok Kerja <i>Stringing Strungback</i>	36
4.2.2.1 Availability Ratio.....	36
4.2.2.2 Performance Ratio	38
4.2.2.3 Quality Ratio.....	40
4.2.2.4 Overall Labor Effectiveness	41
BAB V ANALISIS DAN PEMBAHASAN.....	44
5.1 Analisa OLE Sub Assy Side Glue UP dan <i>Stringing Strungback</i>	44
5.2 Analisis Performance Ratio	45
5.3 Analisis Tidak Sinkron Antara <i>Cabinet Side</i> dan <i>Strungback</i> Menggunakan RCA47	
BAB VI KESIMPULAN DAN SARAN	49
6.1 Kesimpulan	49
6.2 Saran	49
DAFTAR PUSTAKA	50
LAMPIRAN.....	52

DAFTAR GAMBAR

Gambar 1.1 Output Side Glue Bulan Oktober	2
Gambar 1.2 Output Side Glue Bulan November	2
Gambar 2.1 Proses OLE	12
Gambar 3.1 Alur Penelitian	20
Gambar 4.1 Grafik Availability Sub Assy Side Glue UP	30
Gambar 4.2 Grafik Performance Sub Assy Side Glue UP	32
Gambar 4.3 Grafik Nilai OLE Sub Assy Side Glue UP	35
Gambar 4.4 <i>Root Cause Tree</i> Rendahnya Nilai Elemen <i>Performance Ratio</i>	36
Gambar 4.5 Grafik Availability Stringing Strungback	37
Gambar 4.6 Grafik Performance Ratio Stringing Strungback	39
Gambar 4.7 Grafik OLE Stringing Strungback	42
Gambar 4.8 Penyebab Masalah Rendahnya Nilai Elemen <i>Performance Ratio</i>	43

DAFTAR TABEL

Tabel 2.1 Perbandingan Penelitian Sebelumnya.....	10
Tabel 4.1 Data Kehilangan Jam Kerja Sub Assy Side Glue UP.....	23
Tabel 4.2 Hasil Produksi 8 Jam Sub Assy Side Glue UP.....	24
Tabel 4.3 Data Produk Cacat Sub Assy Side Glue UP.....	25
Tabel 4.4 Data Kehilangan Jam Kerja Stringing Strungback.....	26
Tabel 4.5 Hasil Produksi 8 Jam Stringing Strungback.....	27
Tabel 4.6 Data Produk Cacat Stringing Strungback.....	28
Tabel 4.7 Hasil Availability Sub Assy Side Glue UP.....	29
Tabel 4.8 Hasil Performance Sub Assy Side Glue UP.....	31
Tabel 4.9 Hasil Quality Ratio Sub Assy Side Glue UP.....	33
Tabel 4.10 Hasil OLE Sub Assy Side Glue.....	34
Tabel 4.11 OLE Kelompok Sub Assy Side Glue UP.....	35
Tabel 4.12 Hasil Availability Stringing Strungback.....	36
Tabel 4.13 Hasil Performance Stringing Strungback.....	38
Tabel 4.14 Hasil Quality Ratio Stringing Strungback.....	40
Tabel 4.15 Hasil OLE Stringing Strungback.....	41
Tabel 4.16 Nilai OLE Stringing Strungback.....	42
Tabel 5.1 Perbandingan Hasil OLE Sub Assy Side Glue UP dan Stringing Strungback	44
Tabel 5.2 Jumlah Stasiun Kerja di kelompok Sub Assy Side Glue UP.....	45