



Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS*




Gambar L-6.1 Kondisi Awal Timbunan 1 m, Tanah Asli 5 m




Gambar L-6.2 Kondisi Awal Timbunan 1 m, Tanah Asli 35 m

**Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS***




**Gambar L-6.3 Kondisi Awal Timbunan 1 m, Tanah Asli 70 m**




**Gambar L-6.4 Kondisi Awal Timbunan 2 m, Tanah Asli 5 m**

**Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS***




**Gambar L-6.5 Kondisi Awal Timbunan 2 m, Tanah Asli 35 m**




**Gambar L-6.6 Kondisi Awal Timbunan 2 m, Tanah Asli 70 m**

Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS*




Gambar L-6.7 Kondisi Awal Timbunan 3 m, Tanah Asli 5 m




Gambar L-6.8 Kondisi Awal Timbunan 3 m, Tanah Asli 35 m

**Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS***




**Gambar L-6.9 Kondisi Awal Timbunan 3 m, Tanah Asli 70 m**



**Gambar L-6.10 Kondisi Awal Timbunan 4 m, Tanah Asli 5 m**

**Lampiran 6 Kondisi Awal Model Geometri pada *PLAXIS***



**Gambar L-6.11 Kondisi Awal Timbunan 4 m, Tanah Asli 35 m**